

IN THE SPECIFICATION:

Please AMEND paragraph [0036] on page 6 of the specification as follows:

The paragraph shows added text with underlining and deleted text with ~~striketrough~~

[0036] In the embodiment described above, the support 20 and the supporting bracket 30 are directly connected. However, ~~a~~-shock absorbers 60 may be provided between the support 20 and the supporting bracket 30.